

Figure5.--Effective thickness of the Piney Point aquifer.